


CORNER RECORD

Document Number 00-318

City of RIVERSIDE

County of RIVERSIDE, California

Brief Legal Description LOT 286, M.B. 22/81-82 RIV. Co.; SEC 1 T3S R6W RANCHO LA SIERRA
(Include: Sec., Twp., Rge., and Meridian or Rancho) SEC 36 T2S R6W M.B. 6/70 RIV. Co.



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey 10/18/2000

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☒

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE SKETCH ON PAGE 2. SOUTHEAST CORNER LOT 286
M.B. 22/81-82 RIV. Co. AND J.E. DAVIDSON FIELD BOOK 790/72.

A description of the physical condition of the monument as found and as set or reset:

SEE SKETCH ON PAGE 2. FOUND 2X2 NO-TAG TOP
BROKEN OFF, REPLACED WITH DURABLE MONUMENT
AND TAG L.S. 5655.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on OCT 30 2000

Signed [Signature] L.S. or R.C.T. Number LS 5655



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 30, 2000 and examined

and filed November 30, 2000

Signed Michael C. Parks Title Senior Land Surveyor



County Surveyor's Comment _____

RECEIVED
DEC 26 2000

THE FILING OF THIS CORNER RECORD
DOES NOT RELIEVE THE SURVEYOR
FROM ANY RESPONSIBILITY OF THE
FILING OF A RECORD OF SURVEY

DEPT. OF
PUBLIC WORKS